

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



Photo # 3160 From entrance to location



Photo # 3161 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad

Location #: 335176



Photo # 3162 Unused supplies