

Inspection Photos

7/10/2023

Operator: LARAMIE ENERGY LLC #10433

Location Number: 383264

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 383264



Photo 1: Photos 1-3 examples showing cuttings on the north end of the Location lack required containment BMPs in accordance with good engineering practices, and Form 2A COAs.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 383264



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 383264



Photo 3: See comments under photo 1. .



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC #10433

Location Number: 383264



Photo 4: BMPs to prevent or contain a spill are missing or insufficient at the porta-johns.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 383264



Photo 5: Signage/labels missing from tanks/battery.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location Number: 383264



Photo 6: BMPs to prevent wildlife access missing from containment BMP.