

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope O-20 Pad**

**Loc ID: 459884**

**Inspection: 696305124**



**Exhibit A**

**CA:** Tumbleweed Debris at Wellheads; see photos. Comply with Rule 606.

**CA Resolution:** Operator reports that tumbleweed debris has been cleaned and cleared from location to comply with Rule 606.



Antelope O-20

**Exhibit A**

**CA:** Unused wood pallet on North Side of Location; see photos. Comply with Rule 606.

**CA Resolution:** Operator reports that wood pallet on the edge of location has been removed to comply with Rule 606.