

Inspection Photos

Location Name: Enduring Day V Ranch 34-1/2 35-1

Location ID: 067-07468



Photo #1. View of leak identified in FIR Document #712700371.



Photo #2. View of completed corrective action.