

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Jul 19, 2023 at 11:42:53 AM  
CO



Jul 19, 2023 at 11:44:49 AM  
CO

Photo # 3365 From entrance to location

Photo # 3366 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 3367 Location



Photo # 3368 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



Photo # 3369 Location



Photo # 5047 From Inspection 708900263 conducted on 04/11/2023 Tank missing required information

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 3-20 Pad

Location ID: 323886



**Photo # 3374 Tank missing required information**