

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 322577

Inspection Document #: 701900944

W2SW Section 19 T3N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Graznak 1-19
Location ID: 322577



Photo 1. 2022 aerial imagery of the well pad (north is up). Note: tank battery to the south (highlighted in blue) is associated with the Butterball B4-19 well API #123-25656.

Inspection Photos
Location Name: Graznak 1-19
Location ID:322577



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Graznak 1-19
Location ID:322577



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Graznak 1-19
Location ID:322577



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with reference area (see photo #5).

Inspection Photos
Location Name: Graznak 1-19
Location ID:322577



Photo 5. Well pad reference area.