

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 310124

Inspection Document #: 701900945

SWSW Section 19 T3N R64W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Butterball 14-19
Location ID: 310124




Photo 1. 2022 aerial imagery of the well pad and access road (north is up).
Note: tank battery (highlighted in blue) is associated with the Butterball B4-19
well API #123-26565.

Inspection Photos
Location Name: Butterball 14-19
Location ID:310124



Photo 2. Overview photo of the access road taken from the northern edge facing south towards the well pad.

Inspection Photos
Location Name: Butterball 14-19
Location ID:310124



Photo 3. Overview photo of the well pad taken at ground level from the northern edge facing south.

Inspection Photos
Location Name: Butterball 14-19
Location ID:310124



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Butterball 14-19
Location ID:310124



Photo 5. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing east. Note: well pad appears consistent with reference area (see photo #6).

Inspection Photos
Location Name: Butterball 14-19
Location ID:310124



Photo 6. Well pad reference area.