

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 326785

Inspection Document #: 701900954

NWSW Section 35 T4N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Mark 12-35
Location ID: 326785



Photo 1. 2022 aerial imagery of the well pad (north is up). Note: tank battery highlighted in blue is associated with the Mark “E” Unit 1 well API #123-12704.

Inspection Photos
Location Name: Mark 12-35
Location ID:326785



Photo 2. Overview photo of the well pad taken at ground level from the western edge facing east.



Inspection Photos
Location Name: Mark 12-35
Location ID:326785



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Mark 12-35
Location ID:326785



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent reference area (see photo 5).

Inspection Photos
Location Name: Mark 12-35
Location ID:326785



Photo 5. Reference area.

