

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327476

Inspection Document #: 701900956

SENW Section 25 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hamilton 22-25
Location ID: 327476



Photo 1. 2022 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: Hamilton 22-25
Location ID:327476



Photo 2. Overview photo of the well pad taken from the northern edge facing south. Note: well pad pasture was difficult to access (horses/lamas in the area). No signs of oil and gas operations observed during inspection.

Inspection Photos
Location Name: Hamilton 22-25
Location ID:327476



Photo 3. Overview photo of the tank battery taken at ground level from the western edge facing east.

Inspection Photos
Location Name: Hamilton 22-25
Location ID:327476



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Hamilton 22-25
Location ID:327476



Photo 5. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: gravel remains at a majority of the tank battery and the site is dominated by kochia. Does not appear consistent with reference area (see photo #6).

Inspection Photos
Location Name: Hamilton 22-25
Location ID:327476



Photo 6. Reference area.