

# Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 328521

Inspection Document #: 701900957

SENW Section 21 T5N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Schneider 22-21  
Location ID: 328521



**Photo 1.** 2022 aerial imagery of the well pad and access road (north is up).  
Note: the tank battery not pictured to the west is associated with the Schneider 1 well API #123-12447.



Inspection Photos  
Location Name: Schneider 22-21  
Location ID:328521



**Photo 2.** Overview photo of the well pad taken at ground level from the western edge facing east.



Inspection Photos  
Location Name: Schneider 22-21  
Location ID:328521



**Photo 3.** Cardinal photos taken from the middle of the tank battery.  
Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Schneider 22-21  
Location ID:328521



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by weedy annual vegetation and does not appear consistent with the adjacent reference area (see photo #5).



Inspection Photos  
Location Name: Schneider 22-21  
Location ID:328521



**Photo 5.** Reference area.





Inspection Photos  
Location Name: Schneider 22-21  
Location ID:328521



**Photo 6.** Overview photos of the access road taken from the southern edge facing north towards the well pad. Note: access road remains unreclaimed with gravel.