

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 327364

Inspection Document #: 701900958

NENW Section 9 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. 2022 aerial imagery of the well pad and tank battery (north is up).
Note: well pad and tank battery shared a disturbance area.

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 2. Overview photo of the well pad taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 3. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 4. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: northern portion of the well pad disturbance area is dominated by a weedy annual vegetation, field bindweed.



Photo 5. Overview photo of the tank battery taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 6. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 7. Cardinal photos taken from the middle of the tank battery. left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent reference area (see photo #8).

Inspection Photos
Location Name: Annie 3-9
Location ID:327364



Photo 8. Reference area.