

Final Reclamation Inspection

July 1st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 319257

Inspection Document #: 701900960

NESW Section 26 T6N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Payne 2-26
Location ID: 319257



Photo 1. 2023 aerial imagery of the well pad and tank battery (north is up).
Note: well pad and tank battery shared a disturbance pad.

Inspection Photos
Location Name: Payne 2-26
Location ID:319257



Photo 2. Overview photo of the well pad and tank battery disturbance.
Note: Photo illustrates that the Operator has failed to remove gravel
and perform final reclamation activities.