

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 27-28 Pad

Location ID: 323912



Photo # 3382 From entrance to location



Photo # 3383 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 27-28 Pad

Location ID: 323912



Photo # 3384 Location

Photo # 3385 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 27-28 Pad

Location ID: 323912



Photo # 3386 Location



Photo # 3387 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 27-28 Pad

Location ID: 323912



Photo # 3389 Open ended load line



Photo # 3390 Open ended load line