

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 1 location



Photo 2 location

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 3 location



Photo 4 WH sign

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 5 WH stained soil has been removed.



Photo 6 WH stained soil has been removed.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 7 TB sign.



Photo 8 TB.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 9 Stained soil inside berm.



Photo 10 Stained soil inside berm.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 11 Stained soil inside berm.



Photo 12 Stained soil inside berm.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322




Photo 13 Rust hole on Crude oil tank.



Photo 14 Horizontal heated separator.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 15 Gas Meter Run.



Photo 16 Gas Meter Run door and frame on the ground/trash.

Inspection Photos
Location Name: A.C.N.O. 2
Location ID: 311322



Photo 17 PWV not in use, Tin Horn not in use.



Photo 18 PWV not in use, Tin Horn not in use.