

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/3NENE

Location ID: 323965

Date: 7/6/2023



Entrance to Location – Photo #05022



SW Corner of Location – Photo #05023

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/3NENE

Location ID: 323965

Date: 7/6/2023



SE Corner of Location – Photo #05024



Wellhead – Photo #05030

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/3NENE

Location ID: 323965

Date: 7/6/2023



Separator – Photo #05029



Tank Battery – Photo #05025

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/3NENE

Location ID: 323965

Date: 7/6/2023



Lack of Stabilization – Photo #05033



Lack of Stabilization – Photo #05034