

Inspection Photos

7/14/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961



July 14, 2023



July 14, 2023

Photo 1: Location overview



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961



Photo 2: Photos taken from the tank battery. Photo shows fluids and what appears to be salts (white, crusty material) within secondary containment; a spill appears to have occurred at the tank battery.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961



Photo 3: See comments under photo 2.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961



Photo 4: Photos examples showing holes/tears observed within the liner; containment BMP lacks integrity; spill observed at battery likely breached containment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location Number: 335961



Photo 5: Example of vegetation on interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources