

Inspection Photos

7/20/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 426478

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 426478



Photo 1: Location overview



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 426478



Photo 2: Secondary containment berm at 500 bbl produced water tank inadequate in size to contain in spill. BMP also does not appear to be sufficiently consolidated/impervious to contain a spill.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 426478



Photo 3: Storage of unused equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 426478



Photo 4: Example of stained soils observed on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 426478




Photo 5: Photos examples showing uncapped/exposed lines observed at separator equipment.



Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 426478




Photo 6: Photo example showing Musk thistle plants observed spread out over the entire interim areas of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources