

Inspection Photos

API: 071-06628

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/20/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06628 | Date: 7/20/2023

Inspection Photos



Photo 1. Facing north toward the location.



Inspection Photos



Photo 2. There is a dripping water leak at the wellhead that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06628 | Date: 7/20/2023

Inspection Photos



Photo 3. Facing northeast along the fill slope which is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06628 | Date: 7/20/2023