

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 7/7/2023



South Side of Location – Photo #05085



North Side of Location – Photo #05086

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 7/7/2023



Wellheads – Photo #05087



Wellhead – Photo #05094

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, SOLVAY-67S96W/2NWSW

Location ID: 334726

Date: 7/7/2023



Jul 7, 2023 at 12:16:50
Parachute CO 81635
United States



Jul 7, 2023 at 12:17:09
Parachute CO 81635
United States

Separators – Photo #05090

Tank Battery – Photo #05091