

Inspection Photos

Location Name: BIHAIN-65N64W/26NWNW

Location #: 330572



Photo #1

Bihain 26-4 (123-19303) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 50 yds.



Photo #2

Bihain 5, 26-4, 26-1, 26-2, 26-3 Battery site

Abandoned: ALL Equipment Removed