

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 7/10/2023



Lease Road Through Location – Photo #05119



Wellheads – Photo #05120



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 7/10/2023



Separators – Photo #05121



Tank Battery – Photo #05122



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SESW

Location ID: 334869

Date: 7/10/2023



**Lack of Stabilization – Photo #05123**



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #05124**