

**Inspection Photos**  
**Location Name: Brown 43-33**  
**API Number: 125-08304**



**1. Well sign. Note inaccurate emergency contact information displayed on sign.**



**2. Wellhead. Note staining around well.**



**Inspection Photos**  
**Location Name: Brown 43-33**  
**API Number: 125-08304**



**3. View of wellhead and released produced water outside fencing.**



**4. View of produced water released from well. Standing fluids and damp ring extending out from source.**

**Inspection Photos**  
**Location Name: Brown 43-33**  
**API Number: 125-08304**



**5. View of Pump Jack and belt guard leaning against fencing in the background.**



**6. View of Digital Gas Meter Run inside equipment cabinet.**



**Inspection Photos**  
**Location Name: Brown 43-33**  
**API Number: 125-08304**



**7. Additional view of release looking North/Northeast directly at Pump Jack.**



**8. Additional view of release looking West/Northwest at Pump Jack.**