

# Inspection Photos

API: 071-06732

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/20/2023



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 1.** Facing southeast toward the location. Perennial vegetation has re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 2.** Facing along the cut slope of the location which is stabilized with perennial vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 3.** Facing southeast toward the reclaimed offsite pit.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 4.** Facing south toward the reclaimed offsite pit. The vegetation has re-established throughout the disturbance area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 5.** Facing northwest toward the reclaimed offsite pit. The vegetation has re-established throughout the disturbance area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06732 | Date: 7/20/2023

## Inspection Photos



**Photo 6.** Beginning of the transect facing south at the location.



**Photo 7.** End of transect facing north at the location.



## Inspection Photos



**Photo 8.** Beginning of the transect facing northeast at the offsite pit.



**Photo 9.** End of transect facing southwest at the offsite pit.



## Inspection Photos



**Photo 10.** Beginning of the transect facing southeast at the reference area.



**Photo 11.** End of transect facing northwest at the reference area.



