


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad
Location ID: 335146



**Location Overview: Location is within High Priority/Density
Habitat areas.**

Section/Township/Range: 18 6S94W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad
Location ID: 335146



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad
Location ID: 335146



Photo # 3586 Wattles need maintenance (S/SW area of location)




Photo # 3589 Wattles need maintenance (S/SW area of location)

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad
Location ID: 335146



**Photo # 3590 Erosion & transport of sediment off location
(S/SW area of location)**



**Photo # 3591 Erosion & transport of sediment off location
(S/SW area of location)**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad
Location ID: 335146



**Photo # 3587 Erosion & transport of sediment off location
(S/SW area of location)**



**Photo # 3588 Erosion & transport of sediment off location
(S/SW area of location)**