

# Final Reclamation and Stormwater Inspection

Date: 07/19/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 327020

Inspection Document #: 708200394

Weld County, CO

SENW Section 3 T8N R58W

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Lilli Unit 6-3  
Location ID: 327020



**Photo 1.** Taken at the entrance, off the county road. Undesirable vegetation (e.g. russian thistle, field bindweed, downy brome) were observed to be growing throughout the reclaimed location. Additional management of undesirable species is required in order to meet Rule 1004 standards.



Inspection Photos  
Location Name: Lilli Unit 6-3  
Location ID: 327020



**Photo 2.** Portions of the reclaimed location appear to be progressing towards Rule 1004 standards with evidence of desirable perennial species (blue grama, buffalo grass, etc). Additional reclamation activities are required to manage undesirable species within the reclaimed area.



Inspection Photos  
Location Name: Lilli Unit 6-3  
Location ID: 327020



**Photo 3.** Center portions of the reclaimed area are experiencing exposed/bare soil.



Inspection Photos  
Location Name: Lilli Unit 6-3  
Location ID: 327020



**Photo 4.** Taken from the southern portion of the location; see comments in Photos 2 & 3.



Inspection Photos  
Location Name: Lilli Unit 6-3  
Location ID: 327020



**Photo 5.** Taken from the location facing southeast towards the access road. Weedy debris and undesirable species observed throughout the access road.