

Final Reclamation and Stormwater Inspection

Date: 07/19/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 326752

Inspection Document #: 708200396

Weld County, CO

SESE Section 3 T8N R58W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lilli 16-3
Location ID: 326752



Photo 1. Access road north of the location that will need further reclamation work.

Inspection Photos
Location Name: Lilli 16-3
Location ID: 326752



Photo 2 & 3. Straw wattles left on the location's access road are now considered debris and will need to be removed.



Photo 4. Location overview from the northeast portion. Reclamation work appears to have been performed and the location is progressing towards 1004 Rules with desirable vegetation observed.

Inspection Photos
Location Name: Lilli 16-3
Location ID: 326752



Photo 5. Equipment remains on location and will need to be removed.

Inspection Photos
Location Name: Lilli 16-3
Location ID: 326752



Photo 6. See comments in Photo 5.



Photo 7. Taken from the western portion of the location. Undesirable vegetation (e.g. Cheatgrass) does not appear to have been managed and has dropped seeds.