

Final Reclamation and Stormwater Inspection

Date: 07/19/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 327017

Inspection Document #: 708200398

Weld County, CO

SESW Section 3 T8N R58W

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lill Unit 14-3
Location ID: 327017



Photo 1. Taken from the former access road, facing west. Photo illustrates that cut banks (red line) have not been recontoured and bare/exposed soils are evident. Additional reclamation work will need to be performed in order to stabilize the exposed soils.

Inspection Photos
Location Name: Lill Unit 14-3
Location ID: 327017



Photo 2. Facing southeast; see comments in Photo 1.

Inspection Photos
Location Name: Lill Unit 14-3
Location ID: 327017



Photo 3. Facing north from cut bank area; see comments in Photo 1.

Inspection Photos
Location Name: Lill Unit 14-3
Location ID: 327017



Photo 4. Facing northeast from the former well location. The reclaimed portions of the location appear to be progressing towards Rule 1004 standards with evidence of desirable perennial species observed.