

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWSW

Location ID: 334880

Date: 7/10/2023



NE Corner of Location – Photo #05133



NW Corner of Location – Photo #05134

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWSW

Location ID: 334880

Date: 7/10/2023



SE Corner of Location – Photo #05135



Wellheads – Photo #05136

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, UNOCAL-67S96W/2SWSW

Location ID: 334880

Date: 7/10/2023



Separators – Photo #05139



Tank Battery – Photo #05140