

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: State Antelope 41-3HZ

Loc ID: 422884

Inspection: 696305110



Exhibit A

CA: Stained Soil at Wellhead; see photos. Handle waste in accordance with Rule 906 and conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002.f.(2). D.

CA Resolution: Operator has provided photo evidence of the appropriately cleaned location/equipment and noted that they stained soil has been properly disposed of at this time.

CA: Unmarked Riser at Wellhead; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that the flowline has been plugged and marked with a “future use” tag to comply with Rule 606.

CA: Unused Master Valves at Wellhead; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that the unused master valves at the Wellhead have been removed.

