

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope 14-19 Pad**

**Loc ID: 413458**

**Inspection: 696305116**



Exhibit A

**CA:** Unmarked Riser on East Side of Location; see photos. Comply with Rule 606.

**CA Resolution:** Operator has provided photo evidence and noted that the identified Riser has now been marked with a “future use” tag to appropriately comply with Rule 606.



Exhibit A



Exhibit B

**CA:** Tumbleweed Debris at Wellheads; see photo. Comply with Rule 606.

**CA Resolution:** Operator has reported that the identified tumbleweeds have been cleared from location to comply with Rule 606.