

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope P-17 PAD

Loc ID: 428964

Inspection: 696305112



Exhibit A

CA: East 400 BBL Crude Oil Tanks - Content and Capacity Labels have faded; see photos. Install sign to comply with Rule 605.h.

CA Resolution: Operator has provided photo evidence and noted the two Crude Oil Tanks have new capacity/content labels installed to comply with Rule 605.h.

CA: Unused Production Equipment/Parts on East Side of Location; see photos. Comply with Rule 606.

CA Resolution: Operator has reported that there is active maintenance going on at this facility and this equipment will be reinstalled on the tank battery when completed.

CA: Locate Line Flags on Location; see photos. Comply with Rule 606.

CA Resolution: Operator has requested that the current locate line flags remain in place as there is additional digging is likely to be needed. Field will be sure to remove these flags when maintenance has been completed to comply with Rule 606.



Exhibit A

CA: Day Tank Netting is in disrepair. See photos. Install or repair wildlife protection equipment. Prevent any unauthorized discharge (specify condition if it is E&P waste, improper disposal, trash, etc.) Per Rule 902.b

CA Resolution: Operator has provided photo evidence and noted wildlife protective netting has been appropriately replaced to comply with Rule 902.b, and any surrounding debris has been cleared and removed.