

Inspection Photos

API: 071-06303

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/24/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 7/24/2023

Inspection Photos



Photo 1. Facing north at the access road. There is erosion from the access road which is transporting sediment towards the County Road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 7/24/2023

Inspection Photos



Photo 2. Facing northwest along the main road. Stormwater is pooling in this area causing vehicle rutting and widening of the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 7/24/2023

Inspection Photos



Photo 3. Facing northwest along the main road. Stormwater is pooling in this area causing vehicle rutting and erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 7/24/2023

Inspection Photos



Photo 4. Facing southeast toward the wellsite.



Inspection Photos



Photo 5. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06303 | Date: 7/24/2023