

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 1 – Gas Lift Injection Meter House



Photo 2 – Wellheads – Tumbleweed Debris

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 3 – Wellheads – Tumbleweed Debris



Photo 4 – Unused Rip Rap

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 5 – Frac Sand



Photo 6 – What appears to be Debris from Hydrovac Truck

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 7 – Maintenance Tank



Photo 8 – Capacity Label

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 9 – Separators



Photo 10 – Separators

Inspection Photos
Location Name: Antelope J-20 PAD
Location ID: 430128



Photo 11 – Wellheads



Photo 12 – Signs at Entrance

