

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 pad

Location ID: 322437



Photo # 3686 From entrance to location



Photo # 3699 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 pad

Location ID: 322437



Photo # 3688 Location



Photo # 3689 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH 114 pad

Location ID: 322437




Photo # 3695 Open ended piping on separator unit