

Inspection Photos
Location Name: Seaboard 16-33-6-45
API Number: 095-06119



1. Well sign on Meter Shed door. Emergency contact number is not in service.



2. View of wellhead. Note staining on soil and fluid around base of wellhead.

Inspection Photos
Location Name: Seaboard 16-33-6-45
API Number: 095-06119



3. Close up view of stained soil and oily fluid around bottom of wellhead.



4. Concrete pad (Pump Jack). Note stained and impacted soil around edge of cement pad and encrusted lube oil patches on surface of concrete pad.

Inspection Photos
Location Name: Seaboard 16-33-6-45
API Number: 095-06119



5. Gas Meter Run inside Meter Shed.



6. Undated Chart installed in Meter Box at time of inspection.

Inspection Photos
Location Name: Seaboard 16-33-6-45
API Number: 095-06119

Ominex Meter Test Report

Well Name: Seaboard 16-33-6-45 Date: 7-14-20

Diff. Range: 0 to 100 Static Range: 0 to 150 Plate: .375

Temp Average: 60

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (±50) (125)	75	75 (±50) (125)
0	0	0

Inspector: C. Kat

2023.07.19 16:22

7. View of Meter Calibration/Test Log dated 7/14/20 attached to gas meter.



8. Overview of well location.