

Inspection Photos

Location Name: Garrett 7-33-6-45

API Number: 095-06121



1. Well sign on Meter Shed door. Posted emergency contact phone number does not work.



2. Wellhead. Note debris at wellhead and stained impacted soils around wellhead.

Inspection Photos
Location Name: Garrett 7-33-6-45
API Number: 095-06121



3. Closer view of Wellhead. Note stained soils and crusting on wellhead itself.



4. Concrete pad. Note staining and crusted lube oil on pad. Stained impacted soil around pad.

Inspection Photos
Location Name: Garrett 7-33-6-45
API Number: 095-06121



5. View of Gas Meter Run inside Meter Shed.



6. Chart in Meter Box at time of inspection dated 12-1-22.

Inspection Photos
Location Name: Garrett 7-33-6-45
API Number: 095-06121

Ominex Meter Test Report

Well Name Garrett 7-33-6-45 Date 7-14-20

Diff. Range 0 to 100
Static Range 0 to 150
Temp Average 60

Plate 375

Differential		
Chart Read	Found	Left
0	0	0
100	100	100
50	50	50
0	0	0

Static		
Chart Read	Found	Left
0	0	0
150 (250)	150	150 (250)
75 (150) Ltr	75	75 (150) Ltr
0	0	0

Inspector Caj Vot

2023.07.24 15:43

7. Meter Calibration/Test Log dated 7-14-20.



8. View of one of the two rig anchor markers that are down and need repair.