

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2023

Submitted Date:

07/20/2023

Document Number:

709100062**FIELD INSPECTION FORM**

Loc ID 424418	Inspector Name: Heibel, Krystal	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>8960</u> Name of Operator: <u>BONANZA CREEK ENERGY OPERATING COMPANY</u> Address: <u>410 17TH STREET SUITE #1400</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 8 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	ALL INSPECTIONS
,		Inspections@civiresources.com	All Inspections
S, Nathan	(303) 312-8166	nbennett@civiresources.com	Principal Agent
Krystal Heibel	303-817-5217	krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424419	WELL	PA	12/06/2021	GW	123-34023	Antelope 11-20	EI
424458	WELL	AL	03/06/2014	LO	123-34040	Antelope G-20	EI
424462	WELL	TA	05/10/2019	GW	123-34042	Antelope 22-20	EI
424463	WELL	TA	05/10/2019	GW	123-34043	Antelope 21-20	EI
424464	WELL	TA	05/06/2019	GW	123-34044	Antelope 12-20	EI
427232	WELL	TA	05/15/2019	OW	123-34909	Antelope F-20	EI
427234	WELL	TA	06/13/2019	OW	123-34911	Antelope A-20	EI
427235	WELL	TA	05/15/2019	OW	123-34912	Antelope B-20	EI

General Comment:

This is an environmental inspection of the Bonanza Creek Energy Operating Company LLC's Antelope #11-20 Pad (#424418), including wells Antelope #11-20 (API 123-34023), Antelope #G-20 (API 123-34040), Antelope #22-20 (API 123-34042), Antelope #21-20 (API 123-34044), Antelope #12-20 (API 123-34044), Antelope #F-20 (API 123-34909), Antelope #A-20 (API 123-34911), and Antelope #B-20 (API 123-34912). A third party ECMC representative Krystal Heibel, arrived onsite on July 13, 2023, to perform an Environmental Inspection.

The work site is within the Pronghorn Winter Concentration high priority habitat.

Any corrective actions from previous Forms that have not been addressed are still applicable.
Photos are attached to document site conditions at the time of the inspections

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Illegible wellhead signs, sign at tank battery is not installed properly, and emergency contact number on tanks illegible from a distance.		
Corrective Action:	Install signs to comply with Rule 605.a.	Date:	08/14/2023

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash and debris onsite		
Corrective Action:	Comply with Rule 606.d.	Date:	08/14/2023
Type	WEEDS		
Comment:	Tumbleweeds located throughout the site.		
Corrective Action:	Comply wiith rule 606.c.	Date:	08/14/2023
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on site		
Corrective Action:	Comply with rule 606	Date:	08/14/2023

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment:	No		
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>424419</u>	Type: <u>WELL</u>	API Number: <u>123-34023</u>	Status: <u>PA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>424458</u>	Type: <u>WELL</u>	API Number: <u>123-34040</u>	Status: <u>AL</u>	Insp. Status: <u>EI</u>
Facility ID: <u>424462</u>	Type: <u>WELL</u>	API Number: <u>123-34042</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>424463</u>	Type: <u>WELL</u>	API Number: <u>123-34043</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>424464</u>	Type: <u>WELL</u>	API Number: <u>123-34044</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>427232</u>	Type: <u>WELL</u>	API Number: <u>123-34909</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>427234</u>	Type: <u>WELL</u>	API Number: <u>123-34911</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>
Facility ID: <u>427235</u>	Type: <u>WELL</u>	API Number: <u>123-34912</u>	Status: <u>TA</u>	Insp. Status: <u>EI</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403471790	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189576
709100063	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6189573