

Inspection Photos

**Location Name: OWP- Underwood
Ditch #5**

Location ID: 440411

Date: 7/19/2023



Photo 1: View of approximate well location facing northward. Area is seeded and hydromulched.



Photo 2: View of the central portion of the reclamation area facing northward.



Photo 3: View of reclamation area facing westward.