

Inspection Photos
Location Name: Elkhorn Company B7
Location ID: 456966



Photo 1 Location Entrance.



Photo 2 WH sign.



Inspection Photos
Location Name: Elkhorn Company B7
Location ID: 456966



Photo 3 Weeds growing around the WH.




Photo 4 Weeds growing around the ancillary equip.

Inspection Photos
Location Name: Elkhorn Company B7
Location ID: 456966



Photo 5 Weeds growing around the WH.