



00595330

WELL SITE INSPECTION FORM



WELL NAME Holmes 1-14 API NUMBER 05 - 009 - 5104
OPERATOR Horizon PERMIT NUMBER _____
LOCATION SWSW 14-335-42W COUNTY Baca
FIELD _____ INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) 4 FAIL(N) _____ DATE 9-13-88 FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 11-10-87 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ☒ NO _____ PITS BACKFILLED: YES ☒ NO _____
MATERIAL BURIED: YES ☒ NO _____ NA _____ SITE CLEAN: YES ☒ NO _____
BOND RELEASE OK: YES ☒ NO _____ FED _____ HOLE MARKER: YES _____ NO ☒

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS grass pasture, meter run house near site.

NGPA
Filing Fee

Date Check Received

Oct. 29, 1979

3/1/79

FILING NO(S). 79-498

And/Or

WELL NAME(S) Holmes #1-14

Date of Check 10/24/79

Check # 1687

Amt. \$ 700.⁰⁰

Name of Company Bruce Calder, Inc.

Maker of Check Same

Bank Check Issued On Republic National Bank
(Dallas, Tx)