

TEP  
PA 22-26  
Location ID:  
335232



Well heads



Old signage



TEP  
PA 22-26  
Location ID:  
335232



Well signage is falling apart



Chemical containment is full of fluid



TEP  
PA 22-26  
Location ID:  
335232



**Ground has crack in it to edge of location, sign of lack of stabilization**



**Ground has crack in it to edge of location, sign of lack of stabilization**



TEP  
PA 22-26  
Location ID:  
335232



Ground has crack in it to edge of location, sign of lack of stabilization



Ground has crack in it to edge of location, sign of lack of stabilization