

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope J-20 Pad**

**Loc ID: 430128**

**Inspection: 696305122**



Exhibit A



Exhibit B



Exhibit C



Exhibit D




Exhibit E

**CA:** What appears to be Frac Sand or some type of Solid on South side of Location; see photos. Pollution: Violation to water quality standards and classifications. Comply with reporting requirements in 906 and notify EPS within 24-hrs. Comply with 912 Series Rules.

**CA Resolution:** Environmental Specialist reviewed the location and reported that the area has been appropriately cleared of frac sand and cleaned to now comply with Rules 906 and 912. Reported readings from PID were between 26-335ppm.

**CA:** SE Corner - Solid Waste - What appears to be Solids Waste from Hydrovac Truck; see photos. Pollution: Violation to water quality standards and classifications. Comply with reporting requirements in 906 and notify EPS within 24-hrs. Comply with 912 Series Rules.

**CA Resolution:** Environmental Specialist reviewed the location and reported that waste from the Hydrovac has been appropriately cleared and cleaned from the site to comply with Rules 906 and 912. Reported readings from PID were between 26-335ppm.