

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Antelope P-17 PAD

Loc ID: 428964

Inspection: 696305112



Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: Stained Soil at Compressor; see photos. Handle waste in accordance with Rule 906 and conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.

CA Resolution: Field has addressed the stained soil identified at the compressor. Waste has been cleaned and disposed of appropriately.