

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 1 – Wellhead Sign



Photo 2 – Tanks

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 3 – Tubing PSI – 86.25



Photo 4 – Crude Oil Tanks

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 5 – East Truck Loadout – Stained Soil and Oily Waste



Photo 6 – West Truck Loadout – Stained Soil and Oily Waste

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 7 – Weeds



Photo 8 – Weeds

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 9 – Weeds



Photo 10 – Weeds

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 11 – Supply Storage in SW Corner



Photo 12 – Weeds

Inspection Photos
Location Name: Razor 26 SWD
Location ID: 440165



Photo 13 – Weeds