

Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



Photo #1 – Pad sign.

Photo #2 – Pipeline manifold in SW corner of pad.

Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



Photo #3 – View of tank battery from south.

Photo #4 – View into north end of tank battery secondary containment area.



Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



Photo #5 – Emissions Control Device. Note, red box denotes stabilization and compaction issues remaining from previous inspection (doc #707800316).



Photo #6 – Hangs B1 wellhead, note presence of fluid inside of well cellar. This was also noted in previous inspection (doc #707800316).

Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



Photo #7 - Hangs B3 wellhead, note absence of fluid inside of well cellar.

Photo #8 – Trash outside of wellhead area (1),



Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



Photo #9 – Trash outside of wellhead area (2).



Photo #10 – Separators in southeast corner of pad. Red boxes denote locations of unused flowline risers.



Inspection Photos

Location Name: Hangs B Pad

Location ID: #336022

Inspection Date: September 27, 2023



COGCC Field Inspection
39.53424, -107.67824, 5319.8ft, 70°
07/27/2023 10:33:32 AM

Photo #11 – Marked, unused flowline risers located west of separators.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources