

Inspection Photos

Location Name: EMANCIPATOR-65N64W/22SESE

Location ID: 326836



Photo #1

Emancipator 22-16 (123-13748) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 50 yds.



Photo #2

Emancipator B 22-23, 22-9, 22-10, 22-15, 22-16

Battery site

Abandoned: ALL Equipment Removed