

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: Antelope J-20 Pad**

**Loc ID: 430128**

**Inspection: 696305122**



**Exhibit A**

**CA:** Tank missing Capacity Label; see photos. Install sign to comply with Rule 605.h.

**CA Resolution:** Operator has appropriately installed capacity label to comply with Rule 605.h.



**Exhibit A**



**Exhibit B**



**Exhibit C**



**Exhibit D**

**CA:** Tumbleweed Debris at Wellheads; see photos. Comply with Rule 606.

**CA Resolution:** Operator reports that tumbleweed debris identified at the Wellheads have been properly cleared to comply with Rule 606.