

Inspection Photos
Location Name: Valley Farms B Pad
Location ID: #311643
Inspection Date: July 27, 2023



Photo #1 – Pad sign.



Photo #2 – Tank battery.

Inspection Photos
Location Name: Valley Farms B Pad
Location ID: #311643
Inspection Date: July 27, 2023



Photo #3 – Fluids observed in tank battery secondary containment area.



Photo #4 – Localized accumulation of oily waste on tank valve (1).

Inspection Photos
Location Name: Valley Farms B Pad
Location ID: #311643
Inspection Date: July 27, 2023



Photo #5 - Localized accumulation of oily waste on tank valve (2).



Photo #6 – View of ECD and separators.

Inspection Photos
Location Name: Valley Farms B Pad
Location ID: #311643
Inspection Date: July 27, 2023



Photo #7 – Trash in separator area (1).



Photo #8 - Trash in separator area (2).

Inspection Photos
Location Name: Valley Farms B Pad
Location ID: #311643
Inspection Date: July 27, 2023



Photo #9 - Trash in separator area (3).



Photo #10 – Localized accumulation of oily waste located northeast of wells.