

Inspection Photos
Location Name: Lueking 25-19
API Number: 125-08823



1. Well sign at well location.



2. View of Wellhead.

Inspection Photos
Location Name: Lueking 25-19
API Number: 125-08823



3. Electric motor wired to power but not mounted to Pump Jack base.




4. Pump Jack belt guard on ground inside fencing.

Inspection Photos
Location Name: Lueking 25-19
API Number: 125-08823



5. Location overview.



6. Well sign at remote Gas Meter Run mounted on door.

Inspection Photos
Location Name: Lueking 25-19
API Number: 125-08823



7. View of remote Gas Meter Run.



8. Gas Meter Run inside Meter Shed.