

**Storm Water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Location Overview: Location is approximately 319 yards from Mamm Creek. Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.**

**Section/Township/Range: 32 6S92W**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**North West corner of location.**



**North East corner of location.**



**South West corner of location.**



**South East corner of location.**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 3892 Insufficient BMP's for stockpiled soils on location**



**Photo # 3895 Insufficient BMP's for stockpiled soils on location**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



Jul 27, 2023 at 9:50:12 AM  
CO



Jul 27, 2023 at 9:50:28 AM  
CO

**Photo # 3896 Insufficient BMP's for stockpiled soils on location**

**Photo # 3897 Insufficient BMP's for stockpiled soils on location**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 3901 Culvert needs maintenance/insufficient BMP's (Culvert approximately 1/10<sup>th</sup> of a mile from location on lease road near wattles on lease road)**



**Photo # 3903 Erosion & transport of sediment on lease road (approximately 30-40 yards after 1st switchback on lease road)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 3907 Erosion & transport of sediment on lease road  
(after 1<sup>st</sup> switchback on lease road)**



**Photo # 3908 Erosion & transport of sediment on lease road**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 3910 Erosion & transport of sediment on lease road  
(just after 1<sup>st</sup> switchback on lease road)**



**Photo # 3911 Erosion & transport of sediment on lease road  
(just after 1<sup>st</sup> switchback on lease road)**

**Storm water Management and Erosion control**  
**Location Name: CAERUS PICEANCE LLC N32 Pad**  
**Location #: 334856**



**Photo # 3916 BMP needs maintenance (located at 1<sup>st</sup> switchback on lease road)**



**Photo # 3915 BMP needs maintenance (located at 1<sup>st</sup> switchback on lease road)**